


Vehicle details

VIN	WF0JXXGAH JKE56876	Brand	FORD	Maintenance date	-
Licence Plate	G4-59-FB	Model	FIESTA 1.1 63kW ActieAuto 5d Trend	Maintenance mileage	-
Registration date	09/09/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	156 178 km	Engine size	1084	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	22/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Hankook 195/55/16 Summer 6.5 mm		Hankook 195/55/16 Summer 6.5 mm	
Pirelli 195/55/16 Summer 6.5 mm		Pirelli 195/55/16 Summer 6.0 mm	

Exterior

3		Part	Door	4		Part	Door
		Position	Front left			Position	Back left
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair

5



Part	Tailgate / Boot door
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Replace

●●●

6



Part	Bumper
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

●●

7



Part	Bumper obturator
Position	Back
Damages	Missing
Severity	-
Repair mode	Replace

●●

8



Part	Apron
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●

9



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

10



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●●

11



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

12



Part	Grille
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

●●

13



Part	Grille chrome moulding
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

●●

14



Part	Windscreen
Position	-
Damages	Blister
Severity	-
Repair mode	Replace

●●●

Interior damage

1



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2



Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning