

## Vehicle details

|                   |                    |              |                          |                           |                 |
|-------------------|--------------------|--------------|--------------------------|---------------------------|-----------------|
| VIN               | WF0JXXGAH JKE58826 | Brand        | FORD                     | Maintenance date          | -               |
| Licence Plate     | G3-76-DX           | Model        | FIESTA 1.1 63kW Trend 5d | Maintenance mileage       | -               |
| Registration date | 16/09/2019         | Year         | 2019                     | Exterior Color            | Silver Metallic |
| Odometer          | 138 930 km         | Engine size  | 1084                     | interior Color            | Black           |
| Fuel              | Petrol             | Body Type    | -                        | Next technical inspection | -               |
| Seats             | -                  | Transmission | Manual                   | CO2                       | -               |
| Doors             | 5                  | Gears        | 5                        |                           |                 |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 23/09/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Cruise control          | ✓ |
| GPS system              | ✓ |
| Metallic paint          | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |

## Removable element

|                   |   |
|-------------------|---|
| Spare wheel kit   | ✓ |
| Rear parcel shelf | ✓ |

## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Warranty booklet        | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres

|                                          |                                          |
|------------------------------------------|------------------------------------------|
| Continental 195/55/16 All seasons 5.5 mm | Continental 195/55/16 All seasons 5.5 mm |
| Continental 195/55/16 All seasons 6.0 mm | Continental 195/55/16 All seasons 4.5 mm |

## Exterior

1



|             |                  |
|-------------|------------------|
| Part        | Wing             |
| Position    | Front left       |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

●●

3



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Back left          |
| Damages     | Dent & Chips       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

●●●

6



|             |                       |
|-------------|-----------------------|
| Part        | Upper tailgate / Boot |
| Position    | -                     |
| Damages     | Chemical deposit      |
| Severity    | -                     |
| Repair mode | Lumpsum repair        |

●●●

8



|             |                  |
|-------------|------------------|
| Part        | Bumper           |
| Position    | Front left       |
| Damages     | Scratched        |
| Severity    | Length (cm) > 10 |
| Repair mode | Repair           |

●●

9



|             |                  |
|-------------|------------------|
| Part        | Roof             |
| Position    | -                |
| Damages     | Chemical deposit |
| Severity    | -                |
| Repair mode | Lumpsum repair   |

●●●●

## Interior damage

2



|             |                   |
|-------------|-------------------|
| Part        | Interior cleaning |
| Position    | Front             |
| Damages     | Stained/dirty     |
| Severity    | -                 |
| Repair mode | Cleaning          |

4



|             |           |
|-------------|-----------|
| Part        | Floor mat |
| Position    | Back left |
| Damages     | Missing   |
| Severity    | -         |
| Repair mode | For info  |

5



|             |            |
|-------------|------------|
| Part        | Floor mat  |
| Position    | Back right |
| Damages     | Missing    |
| Severity    | -          |
| Repair mode | For info   |

7



|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Up                       |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Smart Repair             |