


### Vehicle details

VIN	WF0JXXGAH JKP26398	Brand	FORD	Maintenance date	-
Licence Plate	L5-45-BS	Model	FIESTA 1.0 EcoBoost 95pk Titanium - Actie Private	Maintenance mileage	-
Registration date	20/04/2021	Year	2021	Exterior Color	Black Metallic
Odometer	70 375 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

### Inspection Details

Inspection date	18/02/2026	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



### Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


### Removable element

Spare wheel kit	✓
Rear parcel shelf	✓








### Technical Document

Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓



### Tyres



Exterior

<p>1</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 16"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 16"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Alloy wheel 16"																						
Position	Front left																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Door																						
Position	Back left																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
<p>5</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	-	Repair mode	Repair	<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dented	Severity	-	Repair mode	Repair
Part	Bumper																						
Position	Back																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						
Part	Wing																						
Position	Back right																						
Damages	Dented																						
Severity	-																						
Repair mode	Repair																						
<p>7</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Door	Position	Front right	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p>8</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 16"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 16"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Door																						
Position	Front right																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Alloy wheel 16"																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p>9</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Scratched	Severity	-	Repair mode	Repair												
Part	Bonnet																						
Position	-																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						

Interior damage

<p>2</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning		
Part	Interior cleaning												
Position	Front												
Damages	Stained/dirty												
Severity	-												
Repair mode	Cleaning												
<p>3</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Back	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning		
Part	Interior cleaning												
Position	Back												
Damages	Stained/dirty												
Severity	-												
Repair mode	Cleaning												