


Vehicle details

VIN	WF0JXXGAH JKY11783	Brand	FORD	Maintenance date	-
Licence Plate	ZV-65-3N	Model	FIESTA 1.1 63kW ActieAuto 5d Trend	Maintenance mileage	-
Registration date	19/08/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	130 858 km	Engine size	1084	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	04/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

3



●●●

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



●●●

Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



●●

Part	Step plate
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning