


Vehicle details

VIN	WF0JXXGAH JLC07897	Brand	FORD	Maintenance date	-
Licence Plate	H5-61-ZF	Model	FIESTA 1.0 EcoBoost 70kW Connected 5d	Maintenance mileage	-
Registration date	25/06/2020	Year	2020	Exterior Color	Black Metallic
Odometer	136 457 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	04/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 195/55/16 Summer 5.0 mm



Continental 195/55/16 Summer 5.0 mm



Hankook 195/55/16 Summer 5.0 mm

Continental 195/55/16 Summer 6.0 mm

Exterior

1		Part: Door Position: Front left Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair	3		Part: Step plate Position: Front left Damages: Dent & Chips Severity: - Repair mode: For info
4		Part: Door Position: Back left Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair	6		Part: Wing Position: Back left Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair
9		Part: Bumper Position: Back Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	10		Part: Door Position: Front right Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
11		Part: Wheelcap 16" Position: Front right Damages: Missing Severity: - Repair mode: For info	12		Part: Wing Position: Front right Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair
13		Part: Bumper Position: Front Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	14		Part: Bonnet Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
15		Part: Roof Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair	16		Part: Roof wind deflector Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
17		Part: Roof post A/B/C Position: Right Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair			

Interior damage

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

8



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace