


Vehicle details

VIN	WF0JXXGAH JLK18057	Brand	FORD	Maintenance date	-
Licence Plate	J3-28-DZ	Model	FIESTA 1.0 EcoBoost 70kW ST-Line 5d	Maintenance mileage	-
Registration date	13/07/2020	Year	2020	Exterior Color	White Solid
Odometer	158 382 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	20/05/2025	Inspection loc.	Ayvens Veghel		
-----------------	------------	-----------------	---------------	--	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

Spare key	✓
Remote key	✓

Tyres



Exterior

1



Part

Alloy wheel 17"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

●

3



Part

Alloy wheel 17"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

●

4



Part

Bumper

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

Interior damage

2



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning