


Vehicle details

VIN	WF0JXXGAH JMG66027	Brand	FORD	Maintenance date	-
Licence Plate	N7-40-DH	Model	FIESTA 1.0 EcoBoost 100pk Titanium 5d	Maintenance mileage	-
Registration date	23/09/2021	Year	2021	Exterior Color	Silver Metallic
Odometer	74 500 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	21/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✗
Spare wheel kit	✓

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 195/60/15 All seasons 3.0 mm		Michelin 195/60/15 All seasons 3.0 mm	
Michelin 195/60/15 All seasons 5.0 mm		Michelin 195/60/15 All seasons 5.0 mm	

Exterior

3



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Number > 2
Repair mode	Repair

●●●●●

5



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Number > 2
Repair mode	Repair

●●●●●

6



Part	Rear parking sensor
Position	Back
Damages	Missing
Severity	-
Repair mode	Replace

●●

8



Part	Door
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

●●

9



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Number > 2
Repair mode	Repair

●●●●●

10



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●●●●

Interior damage

1



PartSpare key

Position-

DamagesMissing

Severity-

Repair modeReplace

2



PartInterior rear-view mirror

PositionLeft

DamagesBroken

Severity-

Repair modeReplace

4



PartInterior cleaning

Position-

DamagesStained/dirty

Severity-

Repair modeCleaning

7



PartRear parcel shelf

Position-

DamagesMissing

Severity-

Repair modeReplace