


Vehicle details

VIN	WF0JXXGAH JNR74491	Brand	FORD	Maintenance date	-
Licence Plate	R5-25-TF	Model	FIESTA 1.0 EcoBoost 125pk mHEV ST-Line	Maintenance mileage	-
Registration date	25/11/2022	Year	2022	Exterior Color	White Solid
Odometer	83 354 km	Engine size	998	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	01/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 205/45/17 Summer 3.0 mm		Pirelli 205/45/17 Summer 2.0 mm	
Pirelli 205/45/17 Summer 6.0 mm		Pirelli 205/45/17 Summer 6.0 mm	

Exterior

1		Part Alloy wheel 17" Position Front left Damages Scratched Severity - Repair mode Lumpsum repair	4		Part Door Position Back left Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair
8		Part Alloy wheel 17" Position Back right Damages Scratched Severity - Repair mode Lumpsum repair	9		Part Door Position Front right Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair
10		Part Alloy wheel 17" Position Front right Damages Scratched Severity - Repair mode Lumpsum repair	11		Part Bumper Position Front Damages Dent & Chips Severity Diameter (mm) > 20 Repair mode Repair
12		Part Roof Position - Damages Chemical deposit Severity - Repair mode Lumpsum repair			

Interior damage

2		Part Interior cleaning Position Front Damages Stained/dirty Severity - Repair mode Cleaning			
3		Part Interior cleaning Position Back Damages Stained/dirty Severity - Repair mode Cleaning	5		Part Boot carpet Position Back Damages Stained/dirty Severity - Repair mode Cleaning
6		Part Rear parcel shelf retaining strap hook Position Back left Damages Missing Severity - Repair mode Replace	7		Part Rear parcel shelf retaining strap hook Position Back right Damages Missing Severity - Repair mode Replace