

**Vehicle details**

VIN	WF0JXXGAH JNR78020	Brand	FORD	Maintenance date	-
Licence Plate	R4-79-SL	Model	FIESTA 1.0 EcoBoost 125pk mHEV Titanium 5d	Maintenance mileage	-
Registration date	17/11/2022	Year	2022	Exterior Color	Black Metallic
Odometer	79 480 km	Engine size	998	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

**Inspection Details**

Inspection date	21/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



**Generic equipment**

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


**Removable element**

Spare wheel kit	✓
Rear parcel shelf	✓

**Technical Document**

Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓



**Tyres**



**Exterior**

<p>3</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dent &amp; Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Front left	Damages	Dent & Chips	Severity	-	Repair mode	Repair	<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Wing																						
Position	Front left																						
Damages	Dent & Chips																						
Severity	-																						
Repair mode	Repair																						
Part	Door																						
Position	Back right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
<p>5</p>  <p>● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	-	Repair mode	Repair	<p>6</p>  <p>● ● ● ● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Bumper																						
Position	Front																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						
Part	Bonnet																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						

**Interior damage**

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning	<p>2</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Other interior</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table> <p>gerookt in voertuig</p>	Part	Other interior	Position	-	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning																						
Position	Front																						
Damages	Stained/dirty																						
Severity	-																						
Repair mode	Cleaning																						
Part	Other interior																						
Position	-																						
Damages	Stained/dirty																						
Severity	-																						
Repair mode	Cleaning																						