


## Vehicle details

|                   |                    |              |                                            |                           |               |
|-------------------|--------------------|--------------|--------------------------------------------|---------------------------|---------------|
| VIN               | WF0JXXGAH JNS10308 | Brand        | FORD                                       | Maintenance date          | -             |
| Licence Plate     | P8-30-LV           | Model        | FIESTA 1.0 EcoBoost 125pk mHEV Titanium 5d | Maintenance mileage       | -             |
| Registration date | 26/04/2022         | Year         | 2022                                       | Exterior Color            | Blue Metallic |
| Odometer          | 91 157 km          | Engine size  | 998                                        | interior Color            | Black         |
| Fuel              | Hybrid petrol      | Body Type    | -                                          | Next technical inspection | -             |
| Seats             | -                  | Transmission | Manual                                     | CO2                       | -             |
| Doors             | 5                  | Gears        | 6                                          |                           |               |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 02/10/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



### Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| GPS system                 | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |
| Led lighting               | ✓ |

### Removable element

|                   |   |
|-------------------|---|
| Spare wheel kit   | ✓ |
| Rear parcel shelf | ✓ |

### Technical Document

|                         |   |
|-------------------------|---|
| Warranty booklet        | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres

|                                     |                                                                                     |                                     |                                                                                     |                                                                                      |
|-------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Continental 195/60/15 Summer 3.5 mm |  | Continental 195/60/15 Summer 3.0 mm |  |  |
| Michelin 195/60/15 Summer 5.5 mm    |  | Michelin 195/60/15 Summer 5.5 mm    |  |                                                                                      |

## Exterior

1



|             |                     |
|-------------|---------------------|
| Part        | Roof wind deflector |
| Position    | -                   |
| Damages     | Chemical deposit    |
| Severity    | -                   |
| Repair mode | Lumpsum repair      |

2



|             |           |
|-------------|-----------|
| Part        | Bumper    |
| Position    | Back      |
| Damages     | Scratched |
| Severity    | -         |
| Repair mode | Repair    |

3



|             |            |
|-------------|------------|
| Part        | Wing       |
| Position    | Back right |
| Damages     | Scratched  |
| Severity    | -          |
| Repair mode | Repair     |

5



|             |                    |
|-------------|--------------------|
| Part        | Door               |
| Position    | Back right         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

6



|             |           |
|-------------|-----------|
| Part        | Bumper    |
| Position    | Front     |
| Damages     | Scratched |
| Severity    | -         |
| Repair mode | Repair    |

## Interior damage

4



|             |               |
|-------------|---------------|
| Part        | Fabric seat   |
| Position    | Back          |
| Damages     | Stained/dirty |
| Severity    | -             |
| Repair mode | Cleaning      |