

Vehicle details

VIN	WF0JXXGAH JNS11949	Brand	FORD	Maintenance date	-
Licence Plate	R7-83-HZ	Model	FIESTA 1.0 EcoBoost 125pk mHEV Titanium 5d	Maintenance mileage	-
Registration date	14/09/2022	Year	2022	Exterior Color	Black Metallic
Odometer	74 934 km	Engine size	998	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	29/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
-----------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 195/60/15 Summer 6.0 mm



Continental 195/60/15 Summer 6.0 mm



Continental 195/60/15 Summer 5.0 mm



Continental 195/60/15 Summer 5.0 mm



Exterior

1



Part

Roof post A/B/C

Position

Left

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

2



Part

Door

Position

Front left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

3



Part

Door

Position

Back left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

4



Part

Wing

Position

Back left

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

5



Part

Tailgate / Boot door

Position

Up

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

6



Part

Roof wind deflector

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

7



Part

Tailgate / Boot door

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

8



Part

Bumper

Position

Back

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

9



Part

Wing

Position

Back right

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

10



Part

Roof post A/B/C

Position

Right

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

11



Part

Step plate

Position

Back right

Damages

Scratched

Severity

-

Repair mode

For info

12



Part

Door

Position

Back right

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

13



Part

Wing

Position

Front right

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

14



Part

Bonnet

Position

-

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

15



● ●

Part	Front Grill Panel
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

16



● ● ● ●

Part	Bumper
Position	Front
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

17



● ●

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair