



FORD S-MAX: 1WPD005			
Vinnumber:	WF0JXXWPCJKY75956	Versionname:	2.0 TDCi 88kW S/S Business Class
First Registrationdate:	30/07/2019	Fiscalpower:	
Expertise Mileage:	148193	Power Kw:	88
Bodytype:		Body colour	Green
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2109
Fueltype:	Diesel		
Maintenance	NOT OK		
Maintenance	08/09/2020		
Maintenance	34023.0		
Maintenance	dernier selon carnet		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar collapsible
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		
Limited Technical Inspection			
Tyres			
Summer tyres:	235/55/17/103 Y		
	Fr.L.	Vredestein: 4 mm	Fr.R. Vredestein: 4 mm
	Re.L.	Michelin: 4 mm	Re.R. Michelin: 4 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			235/55 R 17 103 Y
Tyre size FR			235/55 R 17 103 Y
Tyre size RL			235/55 R 17 103 Y
Tyre size RR			235/55 R 17 103 Y
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			2480
Tyre make FR			2480
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1771,80
Service, Maintenance, Check			0,00



Roof liner, Stain, Cleaning	28,43
-----------------------------	-------



Seat cover FL, Worn, Check	0,00
----------------------------	------



Interior, Not original part, Check	0,00
------------------------------------	------



Interior, Not original part, Check	0,00
------------------------------------	------



Bumper F, Scratch(es), Repair and paint (complete)	346,88
--	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Wing RL, Dent(s), Paintless dent repair	93,06
---	-------



Door RL, Dent(s), Paintless dent repair	93,06
---	-------



Luggage compartment cover, Missing, Replace	331,15
---	--------



Internal boot lining L, Scratch(es), Smart repair	113,74
---	--------



Internal boot lining R, Scratch(es), Acceptable	0,00
---	------



Boot carpet, Stain, Acceptable	0,00
--------------------------------	------



Boot lid covering R, Scratch(es), Acceptable	0,00
--	------



Tailgate / Boot, Dent(s), Acceptable	0,00
--------------------------------------	------



Bumper R, Dent(s), Repair and paint (complete)	404,88
--	--------



Wing RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Outside rear-view mirror housing R, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Repair and paint (complete)

360,60

