



FORD B-MAX

B-MAX 1.0 EcoBoost

VIN NO WF0KXXERJKFC68994
Registration Number RJKFC68994



MOT Date

2026-08-01

Last Service

2024-06-03

Number of Owners

2

Last Service Mileage

98075

Number of Keys

2

First Registration Date

2016-04-16

Odometer Reading

116524 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250912093735
Inspection Date / Place	2025-09-12 / BCA Oberndorf	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	White	Engine Size (cc)	998
Engine Size	1.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	114
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Front parking sensors	Remote central locking	Stability control	Central locking
Leather steering wheel	Rear parking sensors	USB Socket	Alloys wheels
Auxiliary Socket	Front fog lamps	Remote adjusting wing mirrors	Split folding rear seats
CD Player	Electrically folding wing mirrors	Radio	

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	15
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

6 Schäden



4 Schäden



Component		Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Hood	Bodywork / Dent / Dent	
3	Door / Front Left	Bodywork / Dent / Dent	
4	Seat / Front Right	Interior / Dirty	
5	Seat / Back Center	Interior / Dirty	
6	Fender / Back Left	Paint / Scratch / Line	
7	Tailgate	Paint / Scratch / Scuff	
8	Luggage Space Cover / Back	Interior / Missing	
9	Trunk Carpet	Interior / Dirty	
10	Rocker Panel / Center Right	Paint / Scratch / Scuff	



1. Bumper / Front
Paint / Scratch / Scuff -



2. Hood
Bodywork / Dent / Dent -



3. Door / Front Left
Bodywork / Dent / Dent -



4. Seat / Front Right
Interior / Dirty -



5. Seat / Back Center
Interior / Dirty -



6. Fender / Back Left
Paint / Scratch / Line -



7. Tailgate
Paint / Scratch / Scuff -



8. Luggage Space Cover / Back
Interior / Missing -



9. Trunk Carpet
Interior / Dirty -



10. Rocker Panel / Center Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓
Other Equipments	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)