




FORD GALAXY: 1YLN115			
Vinnumber:	WF0KXXWPCKLD20508	Versionname:	2.0 TDCi 110kW S/S Aut. Titanium
First Registrationdate:	30/09/2020	Fiscalpower:	
Expertise Mileage:	185333	Power Kw:	110
Bodytype:		Body colour	Blue
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3414
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	235/55/17/99 V		
	Fr.L.	Dunlop: 3 mm	Fr.R. Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R. Pirelli: 5 mm
Tyre profile depth FL			3.0
Tyre profile depth FR			5.0
Tyre profile depth RL			4.0
Tyre profile depth RR			5.0
Tyre size FL			235/55 R 17 99 V
Tyre size FR			235/55 R 17 99 V
Tyre size RL			235/55 R 17 99 V
Tyre size RR			235/55 R 17 99 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			257
Tyre make FR			264
Tyre make RL			264
Tyre make RR			264
Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			749,78
Interior, Worn, Acceptable			0,00



Bumper spoiler F, Deformed / Strained, Smart repair 113,74



Windscreen, Stone chip(s), Replace 0,00



Step L, Dent(s) and scratch(es), Spot repair 144,58



Door RL, Scratch(es), Acceptable 0,00



Door FL, Chemical polution, Polish 0,00



Boot lid covering R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Repair and paint (complete) 346,88



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

0,00



Step R, Dent(s) and scratch(es), Spot repair

144,58



Door FR, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Acceptable

0,00

