

Vehicle details

VIN	WF0KXXWPC KLY81022	Brand	FORD	Maintenance date	-
Licence Plate	W68364K	Model	GALAXY Vignale 2,0 EcoBlue SCR Aut. 7-Sitzer 14	Maintenance mileage	-
Registration date	30/11/2020	Year	1000	Exterior Color	Grey Metallic
Odometer	48 722 km	Engine size	1997	interior Color	Black
Fuel	Diesel	Body Type	Passenger van	Next technical inspection	01/11/2025
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	02/06/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
7 seater	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓

Removable element




Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit



Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

2



Part	Bonnet
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

3



●●

Part	Bumper
Position	Front
Damages	Deformed
Severity	-
Repair mode	Replace

4



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

5



●●

Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	Repair

7



●●

Part	Door sill
Position	Back left
Damages	Dented
Severity	-
Repair mode	Repair

8



●●●●

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

10



Part	Roof
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

11



●●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

Interior damage

6



Part	Fabric door lining
Position	Back left
Damages	Cut
Severity	-
Repair mode	Replace

9



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others



12



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

13



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks