


Vehicle details

VIN	WF0KXXWPC KMB19498	Brand	FORD	Maintenance date	-
Licence Plate	KR688DY	Model	GALAXY Titanium 2,0 EcoBlue SCR Aut. 111KW	Maintenance mileage	-
Registration date	24/06/2021	Year	1000	Exterior Color	White Solid
Odometer	196 065 km	Engine size	1997	interior Color	Black
Fuel	Diesel	Body Type	Passenger van	Next technical inspection	01/06/2026
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	28/02/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
7 seater	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element




Technical Document

User manual	✓
Log books	✓
Remote key	✓

Tyres

Winter kit



Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	Diameter (mm) > 10
Repair mode	Replace

2



Part	Bonnet
Position	-
Damages	Stone impact
Severity	Diameter (mm) > 4
Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Replace

4



Part	Wing
Position	Front left
Damages	Stone impact
Severity	-
Repair mode	For info

5



Part	Turning signal side
Position	Left
Damages	Broken
Severity	-
Repair mode	Replace

6



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

7



Part	Door
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

11



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

12



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Replace

13



Part	Door sill
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

15



Part	Roof
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

16



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

17



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

Interior damage

8



Part	Fabric door lining
Position	Back left
Damages	Cut
Severity	-
Repair mode	Replace

9



Part

Interior cleaning

Position

-

Damages

Not carried out

Severity

-

Repair mode

Lumpsum

●

●

●

●

●

●

●

10



Part

Steering wheel

Position

-

Damages

Scratched

Severity

-

Repair mode

For info

14



Part

Fabric door lining

Position

Back right

Damages

Cut

Severity

-

Repair mode

Replace

●

●

18



Part

Remote key

Position

-

Damages

Missing

Severity

-

Repair mode

Replace

●

Others

19



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

20



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint