


Vehicle details

VIN	WF0NXXGCH NKD87729	Brand	FORD	Maintenance date	-
Licence Plate	ZB-84-8T	Model	FOCUS 1.0 EcoBoost 100pk Trend Edition Business	Maintenance mileage	-
Registration date	29/04/2019	Year	2019	Exterior Color	Black Solid
Odometer	116 477 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	25/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Goodyear 205/60/16 Summer 4.5 mm		Goodyear 205/60/16 Summer 4.0 mm	
Goodyear 205/60/16 Summer 5.0 mm		Goodyear 205/60/16 Summer 4.5 mm	

Exterior

1		Part	Wing	2		Part	Wing
		Position	Front left			Position	Back left
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Repair

3



Part	Bumper
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

● ●

4



Part	Spoiler
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace

● ●

5



Part	Door
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	Repair

● ●

6



Part	Door
Position	Front right
Damages	Improper repair
Severity	-
Repair mode	Repair

● ● ●

7



Part	Wing
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

● ●

8



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

● ● ●

9



Part	Spoiler
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

● ●

10



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

● ● ●

Interior damage

11



Part	Interior tailgate lining
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace