


Vehicle details

VIN	WF0NXXGCH NKP09238	Brand	FORD	Maintenance date	-
Licence Plate	H2-85-FX	Model	FOCUS 1.0 EcoBoost 100pk ActieAuto 5d Trend Editio	Maintenance mileage	-
Registration date	22/01/2020	Year	2020	Exterior Color	Blue Solid
Odometer	72 545 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details


Inspection date	09/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Audio System	✓
Led lighting	✓

Removable element



Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

205/60/16 Summer 7.0 mm norauto		205/60/16 Summer 7.0 mm norauto	
Continental 205/60/16 Summer 4.0 mm		Continental 205/60/16 Summer 3.0 mm	

Exterior

2		Part	Wing	3		Part	Bumper
		Position	Front left			Position	Back
		Damages	Scratched			Damages	Scratched
		Severity	Length (cm) > 10			Severity	Length (cm) > 10
		Repair mode	Repair			Repair mode	Repair

5



Part	Upper tailgate / Boot
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Door
Position	Back right
Damages	Hail damaged
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair

Others

9



Part	Damage appraisal
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info