

Vehicle details

VIN	WF0NXXGCH NMJ28858	Brand	FORD	Maintenance date	-
Licence Plate	K5-21-VX	Model	FOCUS 1.0 EcoBo Hybrid 125pk Trend Edit Bus 5d Act	Maintenance mileage	-
Registration date	24/03/2021	Year	2021	Exterior Color	Blue Solid
Odometer	94 715 km	Engine size	999	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details


Inspection date	06/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment	Removable element	Technical Document
Manual air-conditioning ✓	Rear parcel shelf ✓	User manual ✓
Cruise control ✓		Warranty booklet ✓
GPS system ✓		Spare key ✓
Alloy wheel rims ✓		Remote key ✓
Central locking ✓		Sat Nav CD ROM Software ✓
Electric windows ✓		
Park Distance Control ✓		
Audio System ✓		
Led lighting ✓		

Tyres

Pirelli 205/60/16 Summer 5.0 mm



Pirelli 205/60/16 Summer 5.0 mm



Pirelli 205/60/16 Summer 6.0 mm

Pirelli 205/60/16 Summer 6.0 mm

Exterior

<p>2</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Spoiler</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Spoiler	Position	Back	Damages	Scratched	Severity	-	Repair mode	Repair
Part	Door																						
Position	Back left																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Spoiler																						
Position	Back																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						
<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair												
Part	Bonnet																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						

Interior damage

<p>1</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning												
Part	Interior cleaning																						
Position	Front																						
Damages	Stained/dirty																						
Severity	-																						
Repair mode	Cleaning																						
<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>Up</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Interior tailgate lining	Position	Up	Damages	Scratched	Severity	-	Repair mode	Replace	<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>Down</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Interior tailgate lining	Position	Down	Damages	Scratched	Severity	-	Repair mode	Replace
Part	Interior tailgate lining																						
Position	Up																						
Damages	Scratched																						
Severity	-																						
Repair mode	Replace																						
Part	Interior tailgate lining																						
Position	Down																						
Damages	Scratched																						
Severity	-																						
Repair mode	Replace																						