


Vehicle details

VIN	WF0NXXGCH NNB10586	Brand	FORD	Maintenance date	-
Licence Plate	R7-32-NK	Model	FOCUS 1.0 EcoBoost Hybrid Titanium Style 5d 5d	Maintenance mileage	-
Registration date	20/10/2022	Year	2022	Exterior Color	Black Metallic
Odometer	92 181 km	Engine size	999	interior Color	Unknown
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	17/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

2		<table border="0"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	-	Repair mode	Repair	3		<table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Roof	Position	-	Damages	Scratched	Severity	-	Repair mode	Repair
Part	Bumper																								
Position	Back																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								
Part	Roof																								
Position	-																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								

Interior damage

1		<table border="0"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning											
Position	Front											
Damages	Stained/dirty											
Severity	-											
Repair mode	Cleaning											