


### Vehicle details

VIN	WF0NXXGCH NNG36202	Brand	FORD	Maintenance date	-
Licence Plate	S2-45-HN	Model	FOCUS 1.0 EcoBoost Hybrid 125pk Titanium 5d 5d	Maintenance mileage	-
Registration date	25/01/2023	Year	2023	Exterior Color	Grey Metallic
Odometer	80 070 km	Engine size	999	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		


### Inspection Details

Inspection date	07/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment	Removable element	Technical Document
Automated air-conditioning ✓	Spare wheel (wheel & tyre) ✓	Warranty booklet ✓
Cruise control ✓	Rear parcel shelf ✓	Spare key ✓
GPS system ✓		Remote key ✓
Alloy wheel rims ✓		Sat Nav CD ROM Software ✓
Metallic paint ✓		
Central locking ✓		
Electric windows ✓		
Park Distance Control ✓		
Audio System ✓		
Led lighting ✓		

### Tyres

Michelin 205/60/16 Summer 6.0 mm		Michelin 205/60/16 Summer 5.5 mm	
Vredestein 205/60/16 Summer 5.0 mm		Vredestein 205/60/16 Summer 4.5 mm	

Exterior

<p><b>1</b></p>  <p>● ●</p>	<table border="0"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Wing	Position	Front left	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p><b>2</b></p>  <p>● ● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Wing																						
Position	Front left																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Roof																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p><b>3</b></p>  <p>● ●</p>	<table border="0"> <tr><td>Part</td><td>Roof wind deflector</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof wind deflector	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p><b>5</b></p>  <p>● ● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Bumper	Position	Front	Damages	Stone impact	Severity	-	Repair mode	For info
Part	Roof wind deflector																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Bumper																						
Position	Front																						
Damages	Stone impact																						
Severity	-																						
Repair mode	For info																						

Interior damage

<p><b>4</b></p>  <p>● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>Up</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Interior tailgate lining	Position	Up	Damages	Scratched	Severity	-	Repair mode	Smart Repair
Part	Interior tailgate lining										
Position	Up										
Damages	Scratched										
Severity	-										
Repair mode	Smart Repair										