



FORD Focus 2008 Diesel focus 1.6 tdcI Ikon (+) 5p Dpf

VIN NO WF0PXXGCDPAP48786

Registration Number ED034FB



MOT Date

2023-08-10

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2010-09-06

Odometer Reading



107525 km

Country First Registered



Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20251002121601
Inspection Date / Place	2025-10-02 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Silver	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	119

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Alloys wheels	Parcel Shef	Remote central locking
Tyre Mobility Kit	Power assisted steering	Digital Radio	Remote adjusting wing mirrors
Trip Computer	Stability control		


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Winter	
	FULDA	205/55//R16 - 94V / 3 mm
	FULDA	205/55//R16 - 94V / 3 mm
	FULDA	205/55//R16 - 94V / 3 mm
	FULDA	205/55//R16 - 94V / 3 mm

Cosmetic Damage

28 Danni




0 Danni




Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Hood	Bodywork / Dent	
3	Front Light / Front Right	Glass Break / Scratch	
4	Bumper / Front	Bodywork / Breakage	
5	Front Light / Front Left	Glass Break / Scratch	
6	Fender / Front Left	Bodywork / Dent	
7	Rim / Front Left	Out of Bodywork / Scratch	
8	Mirror Shell / Front Left	Paint / Scratch / Line	
9	Door / Front Left	Bodywork / Dent	
10	Door / Front Left	Bodywork / Dent	
11	Door / Back Left	Bodywork / Dent	
12	Rocker Panel / Center Left	Bodywork / Dent	

13	Rim / Back Left	Out of Bodywork / Scratch
14	Fender / Back Left	Bodywork / Dent
15	Bumper / Back	Bodywork / Dent
16	Tailgate	Bodywork / Dent
17	Fender / Back Right	Bodywork / Dent
18	Rim / Back Right	Out of Bodywork / Scratch
19	Door / Back Right	Bodywork / Dent
20	Rocker Panel / Center Right	Bodywork / Dent
21	Door / Front Right	Bodywork / Dent
22	Mirror Shell / Front Right	Paint / Scratch / Line
23	Fender / Front Right	Bodywork / Dent
24	Rim / Front Right	Out of Bodywork / Scratch
25	Pillar / Front Right	Bodywork / Dent
26	Roof	Bodywork / Dent



1. Windshield / Front
Glass Break / Impact -



2. Hood
Bodywork / Dent -



3. Front Light / Front Right
Glass Break / Scratch -



4. Bumper / Front
Bodywork / Breakage -



5. Front Light / Front Left
Glass Break / Scratch -



6. Fender / Front Left
Bodywork / Dent -



7. Rim / Front Left
Out of Bodywork / Scratch -



8. Mirror Shell / Front Left
Paint / Scratch / Line -



9. Door / Front Left
Bodywork / Dent -



10. Door / Front Left
Bodywork / Dent -



11. Door / Back Left
Bodywork / Dent -



12. Rocker Panel / Center Left
Bodywork / Dent -



13. Rim / Back Left
Out of Bodywork / Scratch -



14. Fender / Back Left
Bodywork / Dent -



15. Bumper / Back
Bodywork / Dent -



16. Tailgate
Bodywork / Dent -



17. Fender / Back Right
Bodywork / Dent -



18. Rim / Back Right
Out of Bodywork / Scratch -



19. Door / Back Right
Bodywork / Dent -



20. Rocker Panel / Center Right
Bodywork / Dent -



21. Door / Front Right
Bodywork / Dent -



22. Mirror Shell / Front Right
Paint / Scratch / Line -




23. Fender / Front Right
Bodywork / Dent -



24. Rim / Front Right
Out of Bodywork / Scratch -



25. Pillar / Front Right
Bodywork / Dent -



26. Roof
Bodywork / Dent -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			