

Vehicle details

VIN	WF0PXXGCH PKJ29275	Brand	FORD	Maintenance date	-
Licence Plate	G7-90-PX	Model	FOCUS 1.5 EcoBlue 120pk Trend Edition Bus Wag. 5d	Maintenance mileage	-
Registration date	12/11/2019	Year	2019	Exterior Color	White Solid
Odometer	99 239 km	Engine size	1499	interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	25/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Tow	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 205/60/16 Summer 3.0 mm



Michelin 205/60/16 Summer 3.0 mm



Michelin 205/60/16 Summer 3.0 mm

Michelin 205/60/16 Summer 3.0 mm

Exterior

1



Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

2



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

4



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

9



Part	Bonnet
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

10



Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

3



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

6



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

7



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace