



FORD Focus

Focus Turnier 2.0 EcoBlue Start-Stopp-System Aut.

VIN NO WF0PXXGCHPKP00488
Registration Number CHPKP00488



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2020-04-20

Odometer Reading



141280 km

Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250911083230
Inspection Date / Place	2025-09-11 / BCA Neuss	Cosmetic Grade	1


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	112
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment


USB Socket	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Front parking sensors	Remote central locking	Roof rails	Stability control
Electrictailgate	LED Headlamps	Airbag Status	Anti-lock braking
Cruise control	Digital Radio	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Electrically folding wing mirrors	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front

Cosmetic Damage


4 Schäden



2 Schäden



Component	Damage	Comments
1 Hood	Bodywork / Dent / Dent	
2 Fender / Back Left	Bodywork / Dent / Dent	
3 Steering Wheel / Front	Interior / Scratched	
4 Wing Repeater / Left	Paint / Scratch / Scuff	
5 Fender / Front Right	Bodywork / Dent / Dent	
6 Panel Filling / Back Left	Interior / Scratched	



1. Hood
Bodywork / Dent / Dent -




2. Fender / Back Left
Bodywork / Dent / Dent -



3. Steering Wheel / Front
Interior / Scratched -



4. Wing Repeater / Left
Paint / Scratch / Scuff -



5. Fender / Front Right
Bodywork / Dent / Dent -



6. Panel Filling / Back Left
Interior / Scratched -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Diesel Particulate Filter Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)