


Vehicle details

VIN	WF0PXXGCH PKT15101	Brand	FORD	Maintenance date	-
Licence Plate	G9-74-KJ	Model	FOCUS 1.5 EcoBoost 150pk ST-Line Bus. AT Wagon	Maintenance mileage	-
Registration date	14/10/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	83 656 km	Engine size	1497	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	01/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓



Technical Document

User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 235/40/18 Summer 5.5 mm		Michelin 235/40/18 Summer 5.5 mm	
Michelin 235/40/18 Summer 3.0 mm		Michelin 235/40/18 Summer 2.5 mm	

Exterior

2		Part	Alloy wheel 18"	4		Part	Door
		Position	Front left			Position	Back left
6		Damages	Scratched	7		Damages	Dented
		Severity	-			Severity	Diameter (mm) > 20
8		Repair mode	Lumpsum repair	9		Repair mode	Smart Repair
10		Part	Alloy wheel 18"	11		Part	Bumper
		Position	Front right			Position	Front
12		Damages	Scratched	13		Damages	Scratched
		Severity	-			Severity	Length (cm) > 10
14		Repair mode	Lumpsum repair			Repair mode	Repair
		Part	Bonnet			Part	Roof
		Position	-			Position	-
		Damages	Dent & Chips			Damages	Chemical deposit
		Severity	Diameter (mm) > 20			Severity	-
		Repair mode	Repair			Repair mode	Lumpsum repair
		Part	Spoiler				
		Position	Back				
		Damages	Scratched				
		Severity	Length (cm) > 10				
		Repair mode	Repair				

Interior damage

1



Part	Remote key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

3



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning