


Vehicle details

VIN	WF0PXXGCH PKU52323	Brand	FORD	Maintenance date	-
Licence Plate	H2-14-NV	Model	FOCUS 1.0 EcoBoost 125pk ST-Line Bus. Wagon ActieA	Maintenance mileage	-
Registration date	18/03/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	191 696 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	05/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Goodyear 215/50/17 Summer 7.0 mm		Goodyear 215/50/17 Summer 7.0 mm	
Michelin 215/50/17 Summer 5.0 mm		Michelin 215/50/17 Summer 5.0 mm	

Exterior

1		Part: Wing Position: Front left Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair	2		Part: Door Position: Front left Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair
4		Part: Door Position: Back left Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair	6		Part: Wing Position: Back left Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
9		Part: Bumper Position: Back Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	10		Part: Door Position: Back right Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
11		Part: Door Position: Front right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair	12		Part: Bonnet Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
13		Part: Roof Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair	14		Part: Roof wind deflector Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
15		Part: Bumper Position: Front Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair			

Interior damage

3



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

5



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

8



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

7



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace