

Vehicle details

VIN	WF0PXXGCH PLL31086	Brand	FORD	Maintenance date	-
Licence Plate	J8-23-NJ	Model	FOCUS 1.0 EcoBo Hybr 125pk Trend Edit Bs Wagon 5d	Maintenance mileage	-
Registration date	18/09/2020	Year	2020	Exterior Color	Silver Metallic
Odometer	184 659 km	Engine size	999	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	22/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 205/60/16 Summer 5.0 mm



Continental 205/60/16 Summer 5.5 mm



Pirelli 205/60/16 Summer 4.0 mm

Pirelli 205/60/16 Summer 4.0 mm

Exterior

3



Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

4



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Step plate
Position	Back right
Damages	Dented
Severity	-
Repair mode	For info

7



Part	Wing
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

10



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning


2



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

9



●●●

Part	Damage appraisal
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info