



Ford Focus: P503JG

Vinnumber:	WF0PXXGCHPME19156	Versionname:	Focus 1.5 EcoBlue 88kW Trend Edition Business wagon
First Registrationdate:	25/03/2022	Fiscalpower:	
Expertise Mileage:	169211	Power Kw:	88
Bodytype:		Body colour	Frozen White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Diesel	Parking lot	537
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Manual climate control		Headlights Xenon/LED/Laser
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 92 / H / Aluminium	5,2 mm	Continental	Summer
	Right	205 / 60 / 16 / 92 / H / Aluminium	6,8 mm	Continental	Summer
Rear	Left	205 / 60 / 16 / 92 / H / Aluminium	6,6 mm	Continental	Summer
	Right	205 / 60 / 16 / 92 / H / Aluminium	7,0 mm	Continental	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

User's manual, Missing, Replace

No pictures to display

Interior, Dirty, Cleaning





Interior, Smell, Ozone treatment

No pictures to display

Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Polish



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper trim F, Scratch(es), Replace



Bonnet, Chemical polution, Polish



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)





Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle RR, Scratch(es), Repair and paint (complete)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Luggage compartment cover, Missing, Replace



Tailgate / Boot, Dent(s), Repair and paint (complete)



Bumper R, Crack, Repair and paint (complete)



