

Vehicle details

VIN	WF0PXXGCH PNB08489	Brand	FORD	Maintenance date	-
Licence Plate	X1-77-DP	Model	FOCUS 1.0 EcoBoost Hybrid ST-Line Style Wagon 5d	Maintenance mileage	-
Registration date	19/10/2023	Year	2023	Exterior Color	Black Metallic
Odometer	120 195 km	Engine size	999	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	21/07/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

Spare key	✗
Remote key	✓

Tyres

Hankook 215/50/17 All seasons 3.0 mm		Hankook 215/50/17 All seasons 3.0 mm	
Hankook 215/50/17 All seasons 6.0 mm		Hankook 215/50/17 All seasons 6.0 mm	

Exterior

5



●

●

Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



●

●

●

Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



●

●

Part	Spoiler
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

9



●

●

Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

10



●

●

Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Fabric door lining
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Smart Repair

4



Part	Fabric door lining
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Smart Repair

6



Part	Interior tailgate lining
Position	-
Damages	Broken
Severity	-
Repair mode	Replace