



Expertise

Protocol number: 41342126  
Order No. / Reference: 25099016-1  
Inspection date: 28 Aug 2025

Manufacturer: Ford

Model: Focus Turnier 1.0 EcoBoost Hybrid Aut. COOL&CONNECT

VIN: WF0PXXGCHPNR11180



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.0 EcoBoost Hybrid Aut. COOL&CONNECT	
Vehicle Identification number	WF0PXXGCHPNR11180
Mileage (Read)	37,291 km
First registration	8 Nov 2022
Number of holders	1
Next periodical technical inspection	11/2025
(Report not on hand)	
Power / Engine displacement	92 kw / 999 ccm
Fuel type / Cylinder	Hybrid Petrol / E / 3
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Moondust Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	61 %
Last maintenance on / at	11/2024 at 25,914 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	GP468100
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BUC 00131		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	1,970 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	All-season tyres on Steel rim with wheel cover	Vredestein	6mm / 6mm
2)	205/60 R16 96V	All-season tyres on Steel rim with wheel cover	Vredestein	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit			

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

## Equipment

### Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated - with integrated indicators
- Tires: 6.5 J x 16 design wheels (4) with 205/60 R16 tires in 5-spoke design, in black-silver
- Roof rails, black
- tachometer
- Driver information system with on-board computer, color (10.7 cm screen diagonal)
- Parking brake, electronic
- Speed limiter - Intelligent speed limiter with speed limit display
- Glove compartment, illuminated
- Back window, heater
- Interior lighting with LED technology - front and rear and map reading lights in the front
- Isofix mounting including Top-Tether anchor points on the outer seats of the 2nd row
- Air conditioning, manual
- Headrests 2 front and 3 rear, height adjustable
- LED headlights - LED low beam - LED high beam - LED daytime running lights including integrated LED indicators at the front - LED cornering lights, static, including integrated LED fog lights and maneuvering lights
- Premium front center console - sliding armrest - cup holder including cover - storage compartments - 12-volt and USB port
- Post-Collision Assist: In the event of a severe collision that would, for example, trigger the airbag and in which the driver might be incapacitated, this system initiates the braking process. This reduces the risk of colliding with other obstacles and road users after the collision. The driver can intervene throughout the entire collision and apply the accelerator or brake themselves.
- Seats: Passenger seat, 2-way adjustable
- Seats: Map grid on driver and passenger seat backrests
- Seats: Rear seat backrest foldable, 60 : 40 split
- Start-stop system
- Carpet floor mats front
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control and remote luggage compartment release
- Anti-lock braking system (ABS) with electronic brake-force distribution (EBD)
- Attachment points behind the 2nd row of seats for mounting the safety net
- Hill start assist
- Woven fabric headliner
- Roof spoiler painted in body color
- Electronic Safety and Stability Program (ESP) - with Emergency Brake Assist (EBA) and Traction Control (TCS)
- Electric front and rear windows with overall closing function
- Luggage compartment cover
- Cruise control system
- Transmission: 7-speed PowerShift automatic transmission
- Rear window wiper
- Intelligent Safety System - Front airbags for driver and front passenger - Head-shoulder airbags front and rear - Side airbags for driver and front passenger - Seatbelt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seatbelts on all seats, height-adjustable in the front - Safety pedals
- Leather gear knob
- Steering wheel: 3-spoke design - in Sensico leather look
- Steering column, adjustable in height and reach
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Gasoline particulate filter
- Upholstery: Cloth
- Tire repair kit permitted at max. 80 km/h
- Tire pressure monitoring system (TPMS)
- Headlight assistant with day/night sensor
- Selective driving mode switch - including 3 selectable driving modes: Normal, Sport and Eco
- Power steering electro-mechanical speed-dependent EPAS (Electric Power Assisted Steering)
- Seats: Driver's seat height adjustable with manually adjustable lumbar support
- Seats: Front sports seats with increased lateral support
- 12 volt socket in the luggage compartment
- Side window borders in black
- Unfastened seat belt warning system for the 1st and 2nd row of seats

### Extra equipment



- FordPass Connect including eCall and Wi-Fi hotspot in conjunction with navigation system - Live traffic information
- Paint finish: metallic
- Parking pilot system front and rear
- Removable trailer hitch including ESP trailer stabilization
- Safety partition net for luggage compartment
- Seats: Front seats individually and variably heated
- Tires: 4 all-season tires
- Navigation: Ford SYNC 3 with AppLink, 8" touchscreen and DAB/DAB+ - Ford navigation system with AppLink, 8" touchscreen (20.3 cm screen diagonal) - 6 speakers - Android Auto and Apple CarPlay - Bluetooth hands-free system and audio streaming - Steering wheel controls - Radio player - USB port - Voice control via audio and phone - Acoustic and visual route guidance, dynamic navigation with advanced traffic information system, lane recommendation and road map for Europe

## Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

## Missing parts

### Description

Equipment - Tirefit filler

## Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features  
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.  
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle



## Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

Apparently, no repaired previous damage could be found on the vehicle.

## Comments

Fahrzeug weist rundum erhöhte Lackschichtstärken auf





**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view ([Online link](#))



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres






Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation





Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Missing part 1: Equipment: Tirefit filler - Missing - Replace