


|                                                                                                             |  |                                        |  |                          |  |                                               |  |                                                                                     |               |                                         |  |                                     |                                    |                                                  |  |              |  |                                          |  |                   |  |
|-------------------------------------------------------------------------------------------------------------|--|----------------------------------------|--|--------------------------|--|-----------------------------------------------|--|-------------------------------------------------------------------------------------|---------------|-----------------------------------------|--|-------------------------------------|------------------------------------|--------------------------------------------------|--|--------------|--|------------------------------------------|--|-------------------|--|
| MACADAM ITALY S.R.L.<br><br>Piazza Belgioioso, 2 - 20121 Milano (MI)<br><br>Tel. - Fax<br>Piva: 12729790969 |  |                                        |  | Report No.               |  | Expert's report for<br><b>Alphabet Italia</b> |  |                                                                                     |               | Type of insurance<br><b>Perizia</b>     |  |                                     |                                    |                                                  |  |              |  |                                          |  |                   |  |
|                                                                                                             |  |                                        |  | Policyholder             |  |                                               |  | Opposite party                                                                      |               |                                         |  | Opposite party company              |                                    |                                                  |  |              |  |                                          |  |                   |  |
|                                                                                                             |  |                                        |  | Operation<br><b>2025</b> |  | Claim number                                  |  |                                                                                     | Code / Agency |                                         |  |                                     | Date accident<br><b>26/09/2025</b> |                                                  |  |              |  |                                          |  |                   |  |
|                                                                                                             |  |                                        |  | Expert code              |  | Adjuster code                                 |  |                                                                                     | Policy number |                                         |  |                                     | Injured person can recover the VAT |                                                  |  |              |  |                                          |  |                   |  |
| Date assignment<br><b>26/09/2025</b>                                                                        |  | Date first survey<br><b>30/09/2025</b> |  | Place<br><b>SARONNO</b>  |  | C/O<br><b>RIP</b>                             |  | Repairs<br><b>TO START</b>                                                          |               | Photo                                   |  | Lien in favor of                    |                                    | Expiry date                                      |  |              |  |                                          |  |                   |  |
| Ownership certificate<br><b>Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)</b>                  |  |                                        |  |                          |  |                                               |  |                                                                                     |               |                                         |  |                                     |                                    | Formerly plate                                   |  |              |  |                                          |  |                   |  |
| Lessee / Co-owner                                                                                           |  |                                        |  |                          |  |                                               |  |                                                                                     |               |                                         |  |                                     |                                    | Date of overhaul                                 |  |              |  |                                          |  |                   |  |
| Vehicle (Brand - Model - Version)<br><b>FORD FOCUS 1.5 Ecoblue 120cv Business SW wagon 120CV 5P</b>         |  |                                        |  |                          |  |                                               |  | Plate<br><b>GK917GB</b>                                                             |               | Vin Chassis<br><b>WF0PXXGCHPNS44956</b> |  |                                     |                                    | First Registration<br><b>23/05/2022</b>          |  |              |  |                                          |  |                   |  |
| Usage status<br><b>NON CONOSCIUTO</b>                                                                       |  | Km<br><b>100555</b>                    |  | Tyres %<br><b>70</b>     |  | Color<br><b>NERO</b>                          |  | Type of enamel<br><b>PASTEL/DOUBLE</b>                                              |               |                                         |  | Consistency of damage<br><b>YES</b> |                                    | Type of Expert's report<br><b>NOT DEFINITIVE</b> |  |              |  |                                          |  |                   |  |
| Equipment                                                                                                   |  |                                        |  |                          |  |                                               |  |  |               |                                         |  |                                     |                                    |                                                  |  |              |  |                                          |  |                   |  |
| Approval code                                                                                               |  | For commercial vehicles                |  | Carrying Qls<br><b>0</b> |  | Tare, Q<br><b>0</b>                           |  |                                                                                     |               |                                         |  |                                     |                                    |                                                  |  | Wheelbase    |  | Seats No.<br><b>0</b>                    |  | Axles<br><b>0</b> |  |
| Commercial value (C)                                                                                        |  | Wrecked car value                      |  | Value by difference      |  | Ancillary expenses                            |  |                                                                                     |               |                                         |  |                                     |                                    |                                                  |  |              |  |                                          |  |                   |  |
| Damaged items / restoration operations                                                                      |  |                                        |  |                          |  |                                               |  | SR                                                                                  |               | LA                                      |  | VE                                  |                                    | ME                                               |  | D.M.<br>S.C. |  | Costs of spare parts<br>* (VAT excluded) |  |                   |  |
|                                                                                                             |  |                                        |  |                          |  |                                               |  | Dif                                                                                 |               | Time                                    |  | Dif                                 |                                    | Time                                             |  | Dif          |  | Time                                     |  | Time              |  |
| 1                                                                                                           |  | 2577507                                |  | Front door               |  | L                                             |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2577523                                |  | Rear door                |  | L                                             |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2206875                                |  | rear mudguard            |  | L                                             |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2506884                                |  | Rear hatch               |  |                                               |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2206873                                |  | rear mudguard            |  | R                                             |  | M                                                                                   |               |                                         |  | M                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2577516                                |  | Rear door                |  | R                                             |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2577504                                |  | Front door               |  | R                                             |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2621783                                |  | Front mudguard           |  | R                                             |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2690042                                |  | Windshield               |  |                                               |  | S                                                                                   |               |                                         |  | S                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | Codice Ricambio                        |  | Kit incollaggio          |  |                                               |  |                                                                                     |               |                                         |  |                                     |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 3                                                                                                           |  | 2557752                                |  | Front wheel cap          |  | L                                             |  | S                                                                                   |               |                                         |  | S                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | 2516301                                |  | Rear bumper              |  |                                               |  | L                                                                                   |               |                                         |  | L                                   |                                    |                                                  |  |              |  |                                          |  |                   |  |
| 1                                                                                                           |  | Codice Ricambio                        |  | Tappetino ant sx - PRM   |  |                                               |  |                                                                                     |               |                                         |  |                                     |                                    |                                                  |  |              |  |                                          |  |                   |  |

|                       |                                                        |
|-----------------------|--------------------------------------------------------|
| New for old value (N) | Remarks<br>Pneu FULDA Ecocontrol 205/60r16 (7mm - 6mm) |
|-----------------------|--------------------------------------------------------|