




DNAX4204

DNAX4204 · TURNIER 1.0 ECOBOOST MHEV ST-LINE X. 114 kW/155 PS. 999 cm³. 5 Türen · 10 September 2025 · Bochum (D)

Specifications

License Plate Number	DNAX4204	Fuel Type	Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPRE43117
Model	Focus	Cylinder Capacity	999 ^{cm³}
Model Versions	TURNIER 1.0 ECOBOOST MHEV ST-LINE X. 114 kW/155 PS. 999 cm³. 5 Türen	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	07-10-2024
		Odometer	31.560 ^{Km}
Body Type	5 door hatchback	Numer Of Keys	1
Color	Grey	Interior	Grey
Paint Type	Metallic	Number Headrests	5
Production Year	2024		
KW	114		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	7 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	6 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	7 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Fender – Rear Left



Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Hood



Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Alloy – Right Front



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Skirt - Right

Damage Type

Broken

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Frontdoor - Right

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

Damaged

Repair Type

Spray

Acceptable

No