



FORD Kuga Kuga 2.0 TDCi 4x4

VIN NO WF0RXXGCDR9J32893

Registration Number CDR9J32893



MOT Date

2026-03-01

Last Service

2025-01-29

Number of Owners

3

Last Service Mileage

163386

Number of Keys

2

First Registration Date

2009-02-19

Odometer Reading

167019 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250923131150
Inspection Date / Place	2025-09-23 / BCA Oberndorf	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1997
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	169
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	USB Socket	Alloys wheels	Auxiliary Socket
Cruise control	Front fog lamps	Heated windscreen	Remote central locking
Roof rails	Stability control	Electrically folding wing mirrors	Leather steering wheel
Rear parking sensors	Tow ball	Airbag Status	Anti-lock braking
Bluetooth telephone interface	Diesel particulate filter	Front parking sensors	Remote adjusting wing mirrors
Reversing Camera	Satellite navigation	Xenon headlamps	Keyless Entry
Radio			

Equipment Details


Tow Ball Type	Detachable	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	19	Seat Heating	Front

Wheels & Tyres


Left Front Tyre Depth	7	Right Rear Tyre Depth	7
Left Rear Tyre Depth	7	Right Front Tyre Depth	7

Cosmetic Damage

13 Schäden



2 Schäden



Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Worn - out	
2	Panel Filling / Back Left	Interior / Worn - out	
3	Door Joint / Front Left Bottom	Bodywork / Breakage / Crack	
4	Front Light / Front Left	Anomalyon Element	
5	Front Light / Front Right	Anomalyon Element	
6	Rim / Back Left	Out of Bodywork / Scratch	
7	Door / Front Left	Paint / Scratch / Scuff	
8	Rim / Front Left	Out of Bodywork / Scratch	
9	Door / Front Left	Bodywork / Dent / Dent	
10	Hood	Paint / Poor Previous Repair	
11	Rim / Front Right	Out of Bodywork / Scratch	
12	Rim / Back Right	Out of Bodywork / Scratch	

13	Roof	Paint / Poor Previous Repair
14	Foot step	Paint / Scratch / Scuff
15	Bumper / Back	Paint / Scratch / Scuff



1. Panel Filling / Front Left
Interior / Worn - out -



2. Panel Filling / Back Left
Interior / Worn - out -



3. Door Joint / Front Left Bottom
Bodywork / Breakage / Crack -



4. Front Light / Front Left
Anomalyon Element -



5. Front Light / Front Right
Anomalyon Element -



6. Rim / Back Left
Out of Bodywork / Scratch -




7. Door / Front Left
Paint / Scratch / Scuff -



8. Rim / Front Left
Out of Bodywork / Scratch -



9. Door / Front Left
Bodywork / Dent / Dent -



10. Hood
Paint / Poor Previous Repair -



11. Rim / Front Right
Out of Bodywork / Scratch -



12. Rim / Back Right
Out of Bodywork / Scratch -



13. Roof
Paint / Poor Previous Repair -



14. Foot step
Paint / Scratch / Scuff -



15. Bumper / Back
Paint / Scratch / Scuff -

Mechanical Condition

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	!
Parking Sensors / Cameras Functioning	!		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	NA
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel


Steering | Noise / Anomaly 

Engine

Engine Noise  Fume Quantity 





Power Loss 

Clutch

Clutch Functioning 

General

Test Driven Status Not Performed

-  No troubles detected, good condition or correct tests, according to vehicle age and mileage
-  Damages or malfunction detected that requires repairs by the buyer
-  Not applicable
-  Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)