

Vehicle details

VIN	WF0RXXWPG RJM17201	Brand	FORD	Maintenance date	-
Licence Plate	KO402FX	Model	Transit Connect 1,5 Ecoblue L1 Trend 74KW	Maintenance mileage	-
Registration date	17/07/2019	Year	1000	Exterior Color	White Solid
Odometer	154 165 km	Engine size	1499	interior Color	Black
Fuel	Diesel	Body Type	Panel van	Next technical inspection	01/07/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	04/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Heating seats	✓

Removable element

--	--

Technical Document

User manual	✓
Log books	✓
Remote key	✓

Tyres

Winter kit

Bridgestone 205/60/16 H Winter 2.3 mm		Bridgestone 205/60/16 H Winter 2.2 mm	
Bridgestone 205/60/16 H Winter 2.9 mm		Bridgestone 205/60/16 H Winter 2.8 mm	

Exterior

1		Part	Windscreen	2		Part	Bonnet
		Position	-			Position	-
3		Damages	Stone impact	4		Damages	Scratched
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Repair
3		Part	Bumper	4		Part	Wing
		Position	Front			Position	Front left
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair

5

Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

● ●

6

Part	Side panel
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

● ● ●

7

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Replace

● ● ● ● ●

8

Part	Door Frame seal
Position	Back
Damages	Cut
Severity	-
Repair mode	Replace

● ●

9

Part	Side panel
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

● ● ●

10

Part	Door
Position	Side right
Damages	Scratched
Severity	-
Repair mode	For info

11

Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

12

Part	Door sill
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

● ●

13

Part	Roof
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

● ● ●

Interior damage

14



Part	Remote key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

15



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others



16



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

17



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks