



**Ford Mustang: P833TR**

Vinnumber:	<b>WF0TK1E71NMA10457</b>	Versionname:	<b>Mustang Mach-E 216kW/ 98,8kWh Extended RWD automaat</b>
First Registrationdate:	<b>15/06/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>180220</b>	Power Kw:	<b>216</b>
Bodytype:		Body colour:	<b>Premium Metaallak: Dark Matter Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>329</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Telephone equipment
GPS		Lining leather
Autom climate control		Panoramic roof
Windows electric F		Central consol F
Radio multimedia		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 60 / 18 / 100 / V / Aluminium	5,3 mm	Continental	Summer
	Right	225 / 60 / 18 / 100 / V / Aluminium	5,0 mm	Continental	Summer
Rear	Left	225 / 60 / 18 / 100 / V / Aluminium	4,3 mm	Continental	Summer
	Right	225 / 60 / 18 / 100 / V / Aluminium	4,5 mm	Continental	Summer

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>

**Door RL, Scratch(es), Repair and paint (complete)**



**Door FL, Scratch(es), Repair and paint (complete)**



Wing RL, Dent(s), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)

