



Ford Mustang: L806PX

Vinnnummer:	WF0TK3SU2MMA16661	Versionname:	Mustang Mach-E 248kW/ 98,8kWh Extended AWD automaat
First Registrationdate:	13/07/2021	Fiscalpower:	
Expertise Mileage:	52909	Power Kw:	248
Bodytype:		Body colour:	Premium Metaallak: Carbonized Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	416
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Lining leather
GPS		Panoramic roof
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Tow bar removable

Degree of wear

225/55/19/108 H				
Summer tyres:	Fr.L.	Bridgestone: 5,6 mm	Fr.R.	Bridgestone: 5,7 mm
	Re.L.	Bridgestone: 4,8 mm	Re.R.	Bridgestone: 4,8 mm
Tyre profile depth FL				5.6
Tyre profile depth FR				5.7
Tyre profile depth RL				4.8
Tyre profile depth RR				4.8
Tyre size FL				225/55 R 19 108 H
Tyre size FR				225/55 R 19 108 H
Tyre size RL				225/55 R 19 108 H
Tyre size RR				225/55 R 19 108 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Door FL, Bad repair, Repair and paint (complete)



Wheel arch cover RL, Scratch(es), Replace



Bumper spoiler F, Dent(s) and scratch(es), Replace and paint



Bonnet, Stone chip(s), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Door FR, Dent(s), Repair and paint (complete)



Roof pillar R, Scratch(es), Repair and paint (complete)



Roof pillar R, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Smart repair

