



Ford Transit (Segm. B3): 1VVL749

Vinnumber:	WF0XXXTTGXKC28372	Versionname:	Transit 350L L3H2 Trend 2.0TD 130pk/cv FWD
First Registrationdate:	13/03/2019	Fiscalpower:	
Expertise Mileage:	115412	Power Kw:	96
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Type of Tow bar	Tow bar fixed
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	N.A.		

Tyres

235/65/16/115 R				
Winter tyres:	Fr.L.	Bridgestone: 3,1 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 7,2 mm	Re.R.	Bridgestone: 8,5 mm
Tyre profile depth FL				3.1
Tyre profile depth FR				3.0
Tyre profile depth RL				7.2
Tyre profile depth RR				8.5
Tyre size FL				235/65 R 16 115 R
Tyre size FR				235/65 R 16 115 R
Tyre size RL				235/65 R 16 115 R
Tyre size RR				235/65 R 16 115 R
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Missing, Replace



Interior, Dirty, Cleaning



Interior, Worn, Check



Door panel RR, Hole, Replace



Seat cover FL, Burned, Replace



Wing trim RL, Broken, Replace



Door FL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Boot door lining L, Hole, Replace



Boot door lining L, Hole, Replace



Boot door lining R, Hole, Replace



Boot door lining R, Hole, Replace



Bumper R, Deformed / Strained, Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Mirror side repeater R, Crack, Replace



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Acceptable



Wing trim RR, Scratch(es), Replace



Roof, Dent(s) and scratch(es), Repair and paint (complete)

