

Vehicle details

VIN	WF0XXXTTG XKK60417	Brand	FORD	Maintenance date	-
Licence Plate	V8-35-XS	Model	TRANSIT GB 290 L2H2 TDCi 105pk FWD Trend	Maintenance mileage	-
Registration date	08/04/2019	Year	2019	Exterior Color	White Solid
Odometer	168 246 km	Engine size	1995	interior Color	Grey
Fuel	Diesel	Body Type	Panel van	Next technical inspection	-
Seats	3	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	06/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Tow	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓



Removable element

Spare wheel kit	✓
-----------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Continental 215/65/15 Summer 3.5 mm		Continental 215/65/15 Summer 3.5 mm	
Michelin 215/65/15 Summer 5.5 mm		Michelin 215/65/15 Summer 5.5 mm	

Exterior

1		Part	Wing	3		Part	Step plate
		Position	Front left			Position	Left
		Damages	Chemical deposit			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Lumpsum repair			Repair mode	For info

4		PartApron PositionLeft DamagesChemical deposit Severity- Repair modeLumpsum repair	5		PartWing PositionBack left DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair
6		PartDoor PositionBack left DamagesChemical deposit Severity- Repair modeLumpsum repair	7		PartDoor PositionBack right DamagesChemical deposit Severity- Repair modeLumpsum repair
8		PartTipper body Position- DamagesClear Severity- Repair modeFor info	9		PartLower wing PositionBack right DamagesScratched Severity- Repair modeRepair
10		PartDoor PositionSide right DamagesDent & Chips Severity- Repair modeRepair	11		PartDoor PositionFront right DamagesScratched Severity- Repair modeRepair
12		PartUnpainted bumper PositionFront DamagesChemical deposit Severity- Repair modeLumpsum repair	13		PartBumper PositionFront left DamagesChemical deposit Severity- Repair modeLumpsum repair
14		PartBonnet Position- DamagesChemical deposit Severity- Repair modeLumpsum repair	15		PartRoof Position- DamagesRusty SeverityDiameter (mm) > 4 Repair modeLumpsum repair

Interior damage

2		PartInterior cleaning PositionFront DamagesStained/dirty Severity- Repair modeCleaning	16		PartOther interior Position- DamagesChemical deposit Severity- Repair modeFor info stikkerresten buitenkant
---	---	--	----	--	--