

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	285567
License plate	2APR387
Vehicle identification number	WF0YXTTGYMM45681
Dossier	2021 151 018
Make	Ford 300S TD 130 Tr.
Mileage	170416.00
First registration	04/06/2021
	16/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	



DAMAGES

Damages	Type	Acceptable
875	LCV Lettering Removal // L	N
86	Door Front Left // Polish	Y
174	Light / Rear Right / Replace	N
226	Side View Mirror Right / Shell / Replace Painted	N
304	Rear Loading Door Right // Repair & Painting	Y
324	Wheel Rear Left / Wheel Cover / Replace	N
412	Seat Front Left / Bottom Coating / Replace	N
883	Key Price Range 2 //	N

Damage Pictures




Rear Loading Door Right // Repair & Painting-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Door Front Left // Polish-scratch



Light / Rear Right / Replace-cracked



Side View Mirror Right / Shell / Replace Painted-cracked



Seat Front Left / Bottom Coating / Replace-hole



LCV Lettering Removal // L-