



## SMART smart smart & passion

VIN NO WME01MC012H090471  
Registration Number 012H090471



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



### Inspection Report Summary

Customer	BCA Online	Report Number	P20250924150923
Inspection Date / Place	2025-09-24 / Dello Lübeck	Cosmetic Grade	5

### Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	599
Engine Size	0.6	No of Doors	2
Body Type	Coupe	Drive Train	Rear
Seat Colour		No of Seats	2
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

### Vehicle History & Documents


Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			











Equipment

USB Socket	Anti-lock braking	Remote central locking	CD Player
Radio	Airbag Status	Auxiliary Socket	Stability control
Leather steering wheel			

Equipment Details


Air Conditioning	Yes	Sunroof Type	Fixed Panoramic
------------------	-----	--------------	-----------------

Wheels & Tyres


Left Rear Tyre Depth	7	Right Rear Tyre Depth	7
Left Front Tyre Depth	6	Right Front Tyre Depth	6

Cosmetic Damage

4 Schäden



3 Schäden



1

Component		Damage	Comments
1	Rocker Panel / Center Left	Paint / Scratch / Scuff	
2	Mirror / Front Left	Paint / Chipping	
3	Roof	Missing Part	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Ignition Key	Interior / Not Working	
6	Seat / Front Left	Interior / Burn	
7	Seat / Front Right	Interior / Dysfunctional	





1. Rocker Panel / Center Left  
Paint / Scratch / Scuff -




2. Mirror / Front Left  
Paint / Chipping -




3. Roof  
Missing Part -



4. Bumper / Back  
Paint / Scratch / Scuff -




5. Ignition Key  
Interior / Not Working -



6. Seat / Front Left  
Interior / Burn -





7. Seat / Front Right  
Interior / Dysfunctional -



## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

### Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	!
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)