



# SMART smart smart & pulse

VIN NO WME01MC01YH020548  
Registration Number 01YH020548



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-02-01	6	2	200660 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2000-10-23	Germany

## Inspection Report Summary

Customer	BCA Online	Report Number	P20250820103452
Inspection Date / Place	2025-08-20 / BCA Neuss	Cosmetic Grade	5

## Vehicle Summary



Vehicle Condition	Non-Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	No
Colour	Black	Engine Size (cc)	599
Engine Size	0.6	No of Doors	2
Body Type	Coupe	Drive Train	Rear
Seat Colour		No of Seats	2
Seat Covering Name	Orange blau	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

## Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Cosmetic Damage

8 Schäden



4 Schäden



Component		Damage	Comments
1	Wing Expander / Back Left	Bodywork / Breakage / Crack	
2	Bumper / Back	Bodywork / Breakage / Crack	
3	Wing Expander / Back Right	Bodywork / Breakage / Crack	
4	Side Panel / Back Right	Paint / Scratch / Scuff	
5	Door / Front Right	Bodywork / Breakage / Crack	
6	Other	Bodywork / Breakage / Crack	
7	Seat / Front Left	Interior / Ripped	
8	Seat / Front Left	Interior / Broken	
9	Floor Carpet	Interior / Ripped	
10	Panel Filling / Front Right	Interior / Broken	
11	Side Panel / Back Left	Bodywork / Dent / Dent	
12	Door / Front Right	Bodywork / Breakage / Crack	





1. Wing Expander / Back Left  
Bodywork / Breakage / Crack -



2. Bumper / Back  
Bodywork / Breakage / Crack -



3. Wing Expander / Back Right  
Bodywork / Breakage / Crack -



4. Side Panel / Back Right  
Paint / Scratch / Scuff -



5. Door / Front Right  
Bodywork / Breakage / Crack -




6.  
Bodywork / Breakage / Crack -






7. Seat / Front Left  
Interior / Ripped -



8. Seat / Front Left  
Interior / Broken -



9. Floor Carpet  
Interior / Ripped -



10. Panel Filling / Front Right  
Interior / Broken -



11. Side Panel / Back Left  
Bodywork / Dent / Dent -



12. Door / Front Right  
Bodywork / Breakage / Crack -

Mechanical Condition

Control Lights			
Display Defect	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
No Dashboard Lights	!		
Engine			
Engine Status / EML	!	Engine Leak Visible	NA
Engine Starts	✓		
Levels			
Coolant Fluid	NA	Brakes Fluid	NA

Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly	!		
Engine			
Engine Noise	!	The Gears Scratch / Skip / Abnormal Operation	!
Power Loss	!		
Brake			
Brake System Anomaly	!		
General			

Test Driven Status      Not Performed

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)