

## SMART smart fortwo smart fortwo cabrio softouch



VIN NO WME4514801K792728 Registration Number 801K792728

**MOT Date** 

Number of Keys

**Odometer Reading** 

**2**026-06-01

2025-07-09

**3** 

291969 km

Last Service

Last Service Mileage

**Number of Owners** 

First Registration Date

Country First Registered

2014-05-06

**P**2

Germany

### **Inspection Report Summary**

| Customer                | BCA Online                 | Report Number  | P20250918125846 |
|-------------------------|----------------------------|----------------|-----------------|
| Inspection Date / Place | 2025-09-18 / BCA Oberndorf | Cosmetic Grade | 1               |

### Vehicle Summary

| Vehicle Condition  | Runner      | VAT Type               | Margin |
|--------------------|-------------|------------------------|--------|
| Fuel Type          | Petrol      | Road Worthy            | Yes    |
| Colour             | White       | Engine Size (cc)       | 999    |
| Engine Size        | 1.0         | No of Doors            | 2      |
| Body Type          | Convertible | Drive Train            | Rear   |
| Seat Colour        |             | No of Seats            | 2      |
| Seat Covering Name |             | Seat Covering          | Cloth  |
| Charging Cables    |             | NEDC CO2 Rating (q/km) | 100    |
| Gearbox Type       | Automatic   |                        |        |

### Vehicle History & Documents

| Service Book Available | Present | Next Service Mileage | km |
|------------------------|---------|----------------------|----|
| Previous Usage         |         | Imported             | No |
| Manufacturer Warrenty  |         |                      |    |










































# Equipment


Right Rear Tyre Depth

5

| Airbag Status          | Anti-lock braking      | Satellite navigation   | Radio |
|------------------------|------------------------|------------------------|-------|
| Alloys wheels          | Remote central locking | Leather steering wheel |       |
| Equipment Details      |                        |                        |       |
| Air Conditioning       | Yes                    | Alloy Wheel Size       | 15    |
| Seat Heating           | Front                  |                        |       |
| Wheels & Tyres         |                        |                        |       |
| Right Front Tyre Depth | 5                      | Left Front Tyre Depth  | 5     |

Left Rear Tyre Depth

## Cosmetic Damage



1 Pillar / Front Left

Paint / Chemical Damage



1. Pillar / Front Left Paint / Chemical Damage -

#### **Mechanical Condition**

| Control Lights                  |               |                      |          |
|---------------------------------|---------------|----------------------|----------|
| Display Defect                  | •             | Service Light        | •        |
| ABS Warning Light               | •             | Airbag Warning Light | <b>⊘</b> |
| Oil Pressure Warning Light      | •             | Brake Warning Light  | •        |
| Power Steering Warning<br>Light | •             | Alternator / Battery | •        |
| No Dashboard Lights             | •             |                      |          |
| Equipments Test                 |               |                      |          |
| Central Locking                 | •             | Electric Windows     | <b>⊘</b> |
| Navigation System               | •             | Audio Equipment      | <b>⊘</b> |
| AC / Heating System             | •             |                      |          |
| Engine                          |               |                      |          |
| Engine Status / EML             | •             | Engine Leak Visible  | NA       |
| Engine Starts                   | •             |                      |          |
| Gearbox                         |               |                      |          |
| Gear Box                        | •             |                      |          |
| Levels                          |               |                      |          |
| Brakes Fluid                    | •             | Coolant Fluid        | •        |
| Test Drive Inspection           |               |                      |          |
| Steering Wheel                  |               |                      |          |
| Steering   Noise / Anomaly      | •             |                      |          |
| Engine                          |               |                      |          |
| Engine Noise                    | •             | Fume Quantity        | <b>②</b> |
| Power Loss                      | •             |                      |          |
| General                         |               |                      |          |
| Test Driven Status              | Not Performed |                      |          |
| <u> </u>                        |               |                      |          |

8/9 - Report Number P20250918125846

No troubles detected, good condition or correct tests, according to vehicle age and mileage

| Damages or malfunction detected that requires repairs by the buyer |
|--|
| NA Not applicable  |
| Not tested   |

### Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

<u>User Guide</u>