

SMART smart fortwo smart fortwo cabrio softouch



VIN NO WME4514801K792728 Registration Number 801K792728

MOT Date

Number of Keys

Odometer Reading

2026-06-01

3

291969 km

Last Service

Last Service Mileage

Number of Owners

First Registration Date

Country First Registered

2025-07-09

2014-05-06

P2

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250918125846
Inspection Date / Place	2025-09-18 / BCA Oberndorf	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	White	Engine Size (cc)	999
Engine Size	1.0	No of Doors	2
Body Type	Convertible	Drive Train	Rear
Seat Colour		No of Seats	2
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	100
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			








































Equipment


Right Rear Tyre Depth

5

Airbag Status	Anti-lock braking	Satellite navigation	Radio
Alloys wheels	Remote central locking	Leather steering wheel	
Equipment Details			
Air Conditioning	Yes	Alloy Wheel Size	15
Seat Heating	Front		
Wheels & Tyres			
Right Front Tyre Depth	5	Left Front Tyre Depth	5

Left Rear Tyre Depth

Cosmetic Damage



1 Pillar / Front Left

Paint / Chemical Damage



1. Pillar / Front Left Paint / Chemical Damage -

Mechanical Condition

Control Lights			
Display Defect	•	Service Light	•
ABS Warning Light	•	Airbag Warning Light	⊘
Oil Pressure Warning Light	•	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	•		
Equipments Test			
Central Locking	•	Electric Windows	②
Navigation System	•	Audio Equipment	⊘
AC / Heating System	•		
Engine			
Engine Status / EML	•	Engine Leak Visible	NA
Engine Starts	•		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•
Test Drive Inspection			
Steering Wheel			
Steering Noise / Anomaly	•		
Engine			
Engine Noise	•	Fume Quantity	②
Power Loss	•		
General			
Test Driven Status	Not Performed		
<u> </u>			

8/9 - Report Number P20250918125846

No troubles detected, good condition or correct tests, according to vehicle age and mileage

Damages or malfunction detected that requires repairs by the buyer
NA Not applicable
Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

<u>User Guide</u>