



## SMART smart forfour smart forfour

VIN NO WME4540311B015330  
Registration Number 311B015330



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



### Inspection Report Summary

|                         |                           |                |                 |
|-------------------------|---------------------------|----------------|-----------------|
| Customer                | BCA Online                | Report Number  | P20250828085033 |
| Inspection Date / Place | 2025-08-28 / Dello Lübeck | Cosmetic Grade | 4               |

### Vehicle Summary

|                    |         |                        |        |
|--------------------|---------|------------------------|--------|
| Vehicle Condition  | Runner  | VAT Type               | Margin |
| Fuel Type          | Petrol  | Road Worthy            | Yes    |
| Colour             | Black   | Engine Size (cc)       | 1332   |
| Engine Size        | 1.3     | No of Doors            | 4      |
| Body Type          | Sedan   | Drive Train            | Front  |
| Seat Colour        |         | No of Seats            | 4      |
| Seat Covering Name | Schwarz | Seat Covering          | Cloth  |
| Charging Cables    |         | NEDC CO2 Rating (q/km) | 138    |
| Gearbox Type       | Manual  |                        |        |

### Vehicle History & Documents

|                        |   |                      |    |
|------------------------|---|----------------------|----|
| Service Book Available | - | Next Service Mileage | km |
| Previous Usage         |   | Imported             | No |
| Manufacturer Warrenty  |   |                      |    |







Equipment

|                        |                   |                        |                   |
|------------------------|-------------------|------------------------|-------------------|
| Tow ball               | Anti-lock braking | Remote central locking | Sunroof           |
| Radio                  | Airbag Status     | Front fog lamps        | Stability control |
| Leather steering wheel |                   |                        |                   |

Equipment Details


|               |                   |                  |     |
|---------------|-------------------|------------------|-----|
| Tow Ball Type | Detachable        | Air Conditioning | Yes |
| Sunroof Type  | Opening Panoramic |                  |     |

Wheels & Tyres


|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 4 | Left Front Tyre Depth | 4 |
| Right Rear Tyre Depth  | 5 | Left Rear Tyre Depth  | 5 |

Cosmetic Damage

19 Schäden



3 Schäden




| Component |                          | Damage                       | Comments |
|-----------|--------------------------|------------------------------|----------|
| 1         | Tailgate                 | Paint / Poor Previous Repair |          |
| 2         | Fender / Front Left      | Bodywork / Dent / Dent       |          |
| 3         | Mirror / Front Left      | Bodywork / Breakage / Crack  |          |
| 4         | Side Panel / Back Left   | Bodywork / Dent / Dent       |          |
| 5         | Tailgate                 | Anomalyon Element            |          |
| 6         | Tailgate                 | Anomalyon Element            |          |
| 7         | Side Window / Back Left  | Anomalyon Element            |          |
| 8         | Roof                     | Bodywork / Dent / Hail Area  |          |
| 9         | Fender / Back Right      | Paint / Scratch / Scuff      |          |
| 10        | Side Panel / Back Right  | Bodywork / Dent / Dent       |          |
| 11        | Side Panel / Back Right  | Bodywork / Dent / Dent       |          |
| 12        | Side Window / Back Right | Anomalyon Element            |          |
| 13        | Mirror / Front Right     | Paint / Scratch / Scuff      |          |

|    |                            |                         |
|----|----------------------------|-------------------------|
| 14 | Bumper / Front             | Paint / Scratch / Scuff |
| 15 | Bumper / Front             | Paint / Scratch / Scuff |
| 16 | Panel Filling / Back Right | Interior / Scratched    |
| 17 | Tailgate                   | Paint / Corrosion       |
| 18 | Bumper / Back              | Paint / Scratch / Scuff |
| 19 | Bumper / Back              | Paint / Scratch / Scuff |
| 20 | Seat / Front Left          | Interior / Holed        |
| 21 | HandBrake Handle           | Interior / Ripped       |
| 22 | Roof                       | Paint / Scratch / Scuff |




1. Tailgate  
Paint / Poor Previous Repair -



2. Fender / Front Left  
Bodywork / Dent / Dent -




3. Mirror / Front Left  
Bodywork / Breakage / Crack -



4. Side Panel / Back Left  
Bodywork / Dent / Dent -



5. Tailgate  
Anomalyon Element -



6. Tailgate  
Anomalyon Element -




7. Side Window / Back Left  
Anomalyon Element -




8. Roof  
Bodywork / Dent / Hail Area -



9. Fender / Back Right  
Paint / Scratch / Scuff -



10. Side Panel / Back Right  
Bodywork / Dent / Dent -



11. Side Panel / Back Right  
Bodywork / Dent / Dent -



12. Side Window / Back Right  
Anomalyon Element -



13. Mirror / Front Right  
Paint / Scratch / Scuff -




14. Bumper / Front  
Paint / Scratch / Scuff -



15. Bumper / Front  
Paint / Scratch / Scuff -




16. Panel Filling / Back Right  
Interior / Scratched -



17. Tailgate  
Paint / Corrosion -



18. Bumper / Back  
Paint / Scratch / Scuff -



19. Bumper / Back  
Paint / Scratch / Scuff -



20. Seat / Front Left  
Interior / Holed -



21. HandBrake Handle  
Interior / Ripped -



22. Roof  
Paint / Scratch / Scuff -

## Mechanical Condition

### Control Lights

|                      |   |                                              |   |
|----------------------|---|----------------------------------------------|---|
| Display Defect       | ✓ | Service Light                                | ! |
| ABS Warning Light    | ! | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light | ✓ | Oil Pressure Warning Light                   | ✓ |
| Brake Warning Light  | ✓ | Power Steering Warning Light                 | ✓ |
| Alternator / Battery | ✓ | No Dashboard Lights                          | ✓ |

### Equipments Test

|                  |   |                               |   |
|------------------|---|-------------------------------|---|
| Central Locking  | ✓ | Main & Spare Keys Functioning | ! |
| Audio Equipment  | ! | AC / Heating System           | ✓ |
| Other Equipments | ✓ |                               |   |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Status / EML | ✓ | Engine Leak Visible | ✓ |
| Engine Starts       | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

|               |    |                                               |    |
|---------------|----|-----------------------------------------------|----|
| Engine Noise  | NA | The Gears Scratch / Skip / Abnormal Operation | NA |
| Fume Quantity |    | Power Loss                                    |    |

Clutch

Clutch Functioning

Brake

Brake System Anomaly NA

General

Test Driven Status NA

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)