



MINI Electric: 2AVU687				
Vinnumber:	WMW11DJ0202R18499	Versionname:		
First Registrationdate:	9/08/2021	Fiscalpower:		
Expertise Mileage:	30510	Power Kw:		
Bodytype:		Body colour		Black
Gearbox:	Automatic	Type of rims (mounted)		Aluminium
Transmission:		Parking lot		2614
Fueltype:	Electric			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Sun Roof electric		
Cruise Control		Panoramic roof		
Steering wheel multifunctional		Luggage cover		
Seats F heated		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting LED	Type of Tow bar		No Tow bar
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	205/45/17/88 W			
	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/45 R 17 88 W
Tyre size FR				205/45 R 17 88 W
Tyre size RL				205/45 R 17 88 W
Tyre size RR				205/45 R 17 88 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259
Assistance equipment				
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	1			
Total cost ex VAT				2153,13
Interior, Worn, Acceptable				0,00



Bonnet, Scratch(es), Repair and paint (complete)	395,90
--	--------



Bumper F, Scratch(es), Repair and paint (complete)	289,07
--	--------



Bumper spoiler F, Scratch(es), Replace	84,08
--	-------



Wing trim FL, Scratch(es), Replace	103,21
------------------------------------	--------



Alloy rim FL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Door FL, Dent(s), Acceptable	0,00
------------------------------	------



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)	157,71
--	--------



Wing RL, Scratch(es), Polish	0,00
------------------------------	------



Alloy rim RL, Scratch(es), Repair and paint (complete)	129,66
--	--------



Charging cable (normal), Missing, Replace	0,00
---	------



Tailgate / Boot, Scratch(es), Polish	0,00
--------------------------------------	------



Bumper R, Dent(s), Acceptable	0,00
-------------------------------	------



Wiper arm rear, Incomplete, Replace	12,31
-------------------------------------	-------



Alloy rim FR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)	157,71
--	--------



Door FR, Dent(s) and scratch(es), Repair and paint (complete)	434,50
---	--------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RR, Scratch(es), Repair and paint (complete)	129,66
--	--------



Wing trim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Wing trim RR, Scratch(es), Polish	0,00
-----------------------------------	------



Wing RR, Repaired, Acceptable	0,00
-------------------------------	------

