


Vehicle details

VIN	WMW21BR05 03N21280	Brand	MINI	Maintenance date	-
Licence Plate	K6-09-VG	Model	Countryman Cooper Automaat 5d	Maintenance mileage	-
Registration date	15/03/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	182 201 km	Engine size	1499	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	22/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 225/50/18 Run-flat 4.0 mm



Pirelli 225/50/18 Run-flat 3.5 mm



Pirelli 225/50/18 Run-flat 7.0 mm

Pirelli 225/50/18 Run-flat 7.0 mm

Exterior

1



Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

2



Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

4



Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



Part	Step plate
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	For info

6



Part	Sill cover
Position	Right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



Part	Door
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



Part	Wing
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

11



Part	Door
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

3



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Smart Repair

7



Part	Other interior
Position	Right
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Dorpel Sierlijst.	