

INSPECTION REPORT

End Of Contract


GENERAL INFO

File	289020
License plate	2ADP853
Vehicle identification number	WMW21BS0503M96326
Dossier	2021026071
Make	Mini Mini Count.Coo.S E ALL4 2
Mileage	139241
First registration	02/03/2021
client availability date	22/07/2025
inspectionDate	28/08/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
107	Door Rear Left / Trim / Replace	Y
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
271	Bumper Front / Trim Left / Replace	N
318	Flat Tyre Kit // Replace	Y
331	Wheel Alloy Rear Right // Repair	N
544	Interior / Floor Covering / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N


Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front / Trim Left / Replace-scratch





Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Flat Tyre Kit // Replace-missing



Interior / Floor Covering / Replace-tear



Door Rear Left / Trim / Replace-bad position



Bumper Front // Painting-scratch



Bumper Front / Spoiler / Replace-scratch + dent