

Date	Mileage	Description
Jun-25	136,213	Klein materiaal & milieu
Feb-25	127,054	de koplampstelinrichting links en rechts
Dec-24	118,884	BMW service standaard omvang
Dec-24	118,884	Klein materiaal & milieu
Dec-24	118,884	controle niveaus
Apr-24	109,612	BMW service standaard omvang
Apr-24	109,612	de remmentest
Apr-24	109,612	Klein materiaal & milieu
Feb-24	106,365	BMW service standaard omvang
Feb-24	106,365	voertuigcheck
Feb-24	106,365	serv motorolie
Feb-24	106,365	serv microfilter
Feb-24	106,365	Klein materiaal & milieu
Feb-24	106,365	de remvloeistof
Feb-24	106,365	ruitenwisserblad voor
Jan-23	67,867	voertuigcheck
Jan-23	67,867	serv motorolie
Jan-23	67,867	serv microfilter
Jan-23	67,867	serv luchtfilter
Jan-23	67,867	de bougies
Jan-22	30,860	serv motorolie
Jan-22	30,860	serv microfilter