



MINI MINI

Mini Cooper S Aut.

VIN NO WMWXM710202E08062
Registration Number 0202E08062



MOT Date

2026-08-01

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250924113534
Inspection Date / Place	2025-09-24 / BCA Neuss	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	123
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	Yes
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Anti-lock braking	Bluetooth telephone interface
Remote adjusting wing mirrors	Satellite navigation	Leather steering wheel	Radio
Rear parking sensors	Airbag Status	Ambientlighting	Auxiliary Socket
Cruise control	Remote central locking	Stability control	LED Headlamps
Rain sensitive windscreen wipers			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

25 Schäden



0 Schäden



Component		Damage	Comments
1	Roof	Bodywork / Dent / Dent	
2	Roof	Bodywork / Dent / Dent	
3	B Pillar / Center Left	Paint / Scratch / Line	
4	Hood	Bodywork / Dent / Dent	
5	Hood	Bodywork / Dent / Dent	
6	Hood	Bodywork / Dent / Dent	
7	Bumper / Front	Paint / Scratch / Scuff	
8	Bumper / Front	Paint / Scratch / Scuff	
9	Bumper / Front	Paint / Scratch / Scuff	
10	Bumper / Front	Paint / Scratch / Scuff	
11	Hood	Bodywork / Dent / Dent	
12	Hood	Bodywork / Dent / Dent	

13	Door / Front Right	Bodywork / Dent / Dent
14	Side Panel / Back Right	Bodywork / Dent / Dent
15	Side Panel / Back Right	Bodywork / Dent / Dent
16	Rim / Back Right	Out of Bodywork / Scratch
17	Tailgate	Bodywork / Dent / Dent
18	Roof	Bodywork / Dent / Dent
19	Roof	Bodywork / Dent / Dent
20	Bumper / Back	Paint / Scratch / Scuff
21	Rim / Back Left	Out of Bodywork / Scratch
22	Rim / Front Left	Out of Bodywork / Scratch
23	Windshield / Front	Glass Break
24	Hood	Bodywork / Dent / Dent
25	Hood	Paint / Scratch / Scuff




1. Roof
Bodywork / Dent / Dent -



2. Roof
Bodywork / Dent / Dent -



3. B Pillar / Center Left
Paint / Scratch / Line -



4. Hood
Bodywork / Dent / Dent -



5. Hood
Bodywork / Dent / Dent -



6. Hood
Bodywork / Dent / Dent -



7. Bumper / Front
Paint / Scratch / Scuff -




8. Bumper / Front
Paint / Scratch / Scuff -



9. Bumper / Front
Paint / Scratch / Scuff -




10. Bumper / Front
Paint / Scratch / Scuff -




11. Hood
Bodywork / Dent / Dent -




12. Hood
Bodywork / Dent / Dent -



13. Door / Front Right
Bodywork / Dent / Dent -



14. Side Panel / Back Right
Bodywork / Dent / Dent -




15. Side Panel / Back Right
Bodywork / Dent / Dent -



16. Rim / Back Right
Out of Bodywork / Scratch -



17. Tailgate
Bodywork / Dent / Dent -



18. Roof
Bodywork / Dent / Dent -



19. Roof
Bodywork / Dent / Dent -




20. Bumper / Back
Paint / Scratch / Scuff -



21. Rim / Back Left
Out of Bodywork / Scratch -



22. Rim / Front Left
Out of Bodywork / Scratch -



23. Windshield / Front
Glass Break -



24. Hood
Bodywork / Dent / Dent -



25. Hood
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Main & Spare Keys Functioning	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	NA
--------------	----	---------------	----

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)