



MINI MINI

Mini Cooper S Aut.

VIN NO WMWXS710702F13797
Registration Number 0702F13797



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-04-01	-	2	155877 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2017-01-31	-

Inspection Report Summary


Customer	BCA Online	Report Number	P20251001093446
Inspection Date / Place	2025-10-01 / BCA Neuss	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	1998
Engine Size	2.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	125

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	Yes
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Auxiliary Socket	Cruise control
Remote adjusting wing mirrors	Satellite navigation	Sunroof	LED Headlamps
Rear parking sensors	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Digital Radio	Remote central locking	Stability control	Leather steering wheel
Rain sensitive windscreen wipers			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front	Sunroof Type	Opening Panoramic

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

14 Schäden



0 Schäden



Component		Damage	Comments
1	Fender / Back Left	Paint / Poor Previous Repair	
2	Door / Back Left	Paint / Poor Previous Repair	
3	Door / Back Left	Paint / Poor Previous Repair	
4	Rocker Panel / Center Left	Paint / Scratch / Scuff	
5	Spoiler / Front	Bodywork / Breakage	
6	Rocker Panel / Center Right	Bodywork / Dent / Dent	
7	Corner Bumper / Back Right	Bodywork / Dent / Dent	
8	Bumper / Back	Bodywork / Dent / Dent	
9	Rim / Back Left	Out of Bodywork / Scratch	
10	Rim / Front Left	Out of Bodywork / Scratch	
11	Rim / Front Right	Out of Bodywork / Scratch	
12	Rim / Back Right	Out of Bodywork / Scratch	


13	Windshield / Front	Glass Break
14	Door / Front Left	Bodywork / Dent / Dent



1. Fender / Back Left
Paint / Poor Previous Repair -




2. Door / Back Left
Paint / Poor Previous Repair -



3. Door / Back Left
Paint / Poor Previous Repair -



4. Rocker Panel / Center Left
Paint / Scratch / Scuff -



5. Spoiler / Front
Bodywork / Breakage -



6. Rocker Panel / Center Right
Bodywork / Dent / Dent -



7. Corner Bumper / Back Right
Bodywork / Dent / Dent -



8. Bumper / Back
Bodywork / Dent / Dent -



9. Rim / Back Left
Out of Bodywork / Scratch -



10. Rim / Front Left
Out of Bodywork / Scratch -




11. Rim / Front Right
Out of Bodywork / Scratch -



12. Rim / Back Right
Out of Bodywork / Scratch -



13. Windshield / Front
Glass Break -



14. Door / Front Left
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	NA
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	NA
--------------	----	---------------	----

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)